63 North Connally Trace

Being Lot Sixteen (16), in Block One (1), of The Connallys, Village of Sterling Ridge, Section Nineteen (19), a subdivision of 23.45 acres of land located in the Isaac Mansfield Survey, A-344 and the James Brown Survey, A-78, Montgomery County, Texas, according to the map or plat thereof recorded in Cabinet X, Sheet 123, of the Map Records of Montgomery County, Texas.

logo



LEGEND

○ 1/2" ROD FOUND

○ 1/2" ROD SET

○ 1" PIPE FOUND

○ 1" PIPE FOUND
□ "X" FOUND/SET
□ 5/8" ROD FOUND

POINT FOR CORNER FENCE POST FOR CORNER

CM CONTROLLING MONUMENT

AC AIR CONDITIONER

PE POOL EQUIPMENT

TE PAD EQUIPMENT

COLUMN

POWER POLE

UNDERGROUND
ELECTRIC

---OHP--OVERHEAD ELECTRIC
POWER
---OES--OVERHEAD ELECTRIC

WOOD FENCE 0.5'
WIDE TYPICAL

OUBLE SIDED WOOD FENCE

EDGE OF GRAVEL
CONCRETE

COVERED AREA

THE WOODLANDS
VILLAGE OF STERLING RIDGE
SEC. 18
CAB. R, SHT. 160-164 1/2" IRF FOR WITNESS S 50°35'17" E 0.64' 5' EASEMENT AREA CC# 9348561 1/2" IRF FOR WITNESS N 43°36'28" E 0.28' 0.2 ON. EASEMENT AREA POOL CC# 9348561 26.2 39.2 1.0' STONE 13.7 RET. WALL 8.9,<mark>0</mark> 25.0 LOT 17 METE 5 18.8 LOT 49 16 TWO STORY STONE AND , o 15.9 **FRAME** LOT 15 10' EASEMENT AREA CC# 9348561 SANITARY SOUTH SEASONS TRACE CIRCLE SEWER ESMT L=78.67' R=225.00' NORTH CONNALLY TRACE 50' R.O.W.

EXCEPTIONS:

NOTE: PROPERTY SUBJECT TO TERMS, CONDITIONS, AND EASEMENTS CONTAINED IN INSTRUMENT RECORDED IN

9348561, 2003-084862, 2003-084863, 2004-109793, 2005-125404, 2008-024822, 2008-032753, 2009-116493, 2010-026343, 2011-076399

NOTES:

NOTE: BEARINGS, EASEMENTS AND BUILDING LINES ARE BY RECORDED PLAT UNLESS OTHERWISE NOTED.

FLOOD NOTE: According to the F.I.R.M. No. 48339C0505 F, this property does lie in Zone X and does not lie within the 100 year flood zone.

This survey is made in conjunction with the information provided by Title Comapny. Use of this survey by any other parties and/or for other purposes shall be at user's own risk and any loss resulting from other use shall not be the responsibility of the undersigned. This is to certify that I have on this date made a careful and accurate survey on the ground of the subject property. The plat hereon is a correct and accurate representation of the property lines and dimensions are as indicated; location and type of buildings are as shown; and EXCEPT AS SHOWN, there are no visible and apparent encroachments or protrusions on the ground.

Drawn	Ву:_	RR
Scale:	1"	= 30'
Date:_	XX-	-XX-XX
GF No.: 01010101		

Job No.

Example



12025 Shiloh Road, Ste. 230 Dallas, TX 75228 P 214,349.9485 F 214,349.2216 Firm No. 10168800 www.cbginctx.com

Accepted by:

Purchaser
Purchaser